	Property is: Single Far	nily 🗹	Duplex	□ Other □		
Date:	9/1/2015	, _	2 apion			
		ealth and s	afety issues	s. The City of Milwaukee, the Redevelopment	Authority, and their rep	resentatives
ake no respo	nsibility for problems discovered	after the ins	spection da	te, or for omissions through error or oversight. leral Block Grant or HOME programs.		
Exterior (Condition Report					
Location	Required Work	_	_	Note/Comments		Cost
Site	Landscaping	n/a 🗌	Yes 🔽	Self Help	\$	300.00
	Steps/Handrails	n/a ✓	Yes 🗌		\$	
	Service walks	n/a ✓	Yes 🗌		\$	
	Fencing	n/a ✓	Yes		\$	
	Parking	n/a ✓	Yes 🗌		\$	
	Retaining walls	n/a ✓	Yes 🗌		\$	
	Other	n/a 🗌	Yes \square		\$	
	Other	n/a	Yes 🗌		\$	
Garage	Singles: repair	n/a	Yes 🗸		\$	1,000.00
	Shingles: Roof over existing	n/a ✓	Yes		\$	
	Shingles:Tear off & re-roof	n/a ✓	Yes 🗌		\$	
	Gutters/downspouts	n/a ✓	Yes 🗌		\$	
	·					
	Flashing		Yes _		\$	400.00
	Eaves	n/a	Yes 🗸		\$	420.00
	Siding	n/a 📙	Yes 🗸		\$	600.00
	Doors	n/a L	Yes 🗸		\$	900.00
	Windows	n/a	Yes 🗸		\$	150.00
	Slab	n/a ✓	Yes		\$	
	Paint	n/a	Yes 🗸		\$	500.00
	Electrical	n/a ✓	Yes 🗌		\$	
Doroboo	Other	n/a	Yes 🗸	Structural repairs	\$	1,000.00
Porches	Roof	n/a ✓	Yes 🗌		\$	
	Deck-upper	n/a ☑	Yes 🗌		\$	
	Decklower	n/a ✓	Yes 🗌		\$	
	Steps/handrails	n/a ✓	Yes 🗌		\$	
	Ceiling	n/a ☑	Yes		\$	
	Guardrails	n/a 🗌	Yes 🗸		\$	750.00
	Structural	n/a ✓	Yes		\$,,,,,
					Ψ	

n/a 🗌 Yes 🗌

Other

\$

House

Chimney	n/a ☐ Yes ✓		\$ 500.00
Shingles: repair	n/a ☑ Yes 🗌		\$
Shingles: Roof over existing	n/a ☑ Yes 🗌		\$
Shingles:Tear off & re-roof	n/a ☐ Yes ✓	North side	\$ 4,000.00
Gutters/downspouts	n/a ☐ Yes ✓	Seal receivers	\$ 100.00
Flashing	n/a ✓ Yes 🗌		\$
Eaves	n/a ☑ Yes □		\$
Siding	n/a ☐ Yes ☑	Siding & trim	\$ 250.00
Storm Doors	n/a ✓ Yes 🗌		\$
Prime ("main") Doors	n/a ☑ Yes ☐		\$
Storm Windows	n/a ☐ Yes ☑		\$ 100.00
Prime ("main") Windows	n/a ☑ Yes 🗌		\$
Paint	n/a ☐ Yes ☑		\$ 1,100.00
Foundation	n/a ☐ Yes ☑	Cement bsmt beam pocket & secure to column	\$ 250.00
Electrical	n/a ☐ Yes ☑	outlet on north side	\$ 100.00
Other	n/a 🗌 Yes 🗌		\$
Other	n/a 🗌 Yes 🗌		\$
Other	n/a 🗌 Yes 🗌		\$
Other	n/a 🗌 Yes 🗌		\$

Exterior: Estimated Cost:* \$
*average contracted cost. Actual costs may vary. Self help will reduce the amount.

12,020.00

Interior Co	ondition Report						
	Unit: Entire unit (single family)	✓				Lower unit of duplex	
Mechanical	Upper unit of duplex Required Work					Other	
Heating	Required Work						
_	Repair/replace boiler	n/a	V	Yes			\$
	Repair radiation	n/a	7	Yes			\$
	Repair/replace furnace	n/a	~	Yes			\$
	Repair ductwork	n/a	V	Yes			\$
	Replace thermostat	n/a	~	Yes			\$
	Repair/replace grilles	n/a		Yes	V		\$ 100.00
Flootvicel	Tune boiler/furn. insp ht exchang	n/a		Yes	V		\$ 350.00
Electrical	Repair/replace receptacles	n/a		Yes	V		\$ 350.00
	Repair/replace switches	n/a	~	Yes			\$
	Repair/replace fixtures	n/a	V	Yes			\$
	Install outlets and circuits	n/a		Yes	V		\$ 200.00
	Install outlets and circuits	n/a	V	Yes			\$
	Install outlets and circuits	n/a	V	Yes			\$
	Install outlets and circuits	n/a	V	Yes			\$
	Upgrade service	n/a	~	Yes			\$
	Other	n/a		Yes	√	Open basement electric jct boxes	\$ 200.00
	Other	n/a		Yes			\$
Plumbing	Repair/replace kitchen sink	n/a	~	Yes			\$
	Repair/replace kitchen sink fauce	n/a	~	Yes			\$
	Repair/replace tub	n/a	V	Yes			\$
	Repair/replace tub faucet	n/a		Yes	V		\$ 400.00
	Repair/replace toilet	n/a	~	Yes			\$
	Repair/replace lavatory	n/a		Yes	V		\$ 500.00
	Repair/replace lavatory faucet	n/a	V	Yes			\$
	Repair/replace wash tub	n/a		Yes	V		\$ 750.00
	Repair/replace wash tub faucet	n/a	~	Yes			\$
	Unclog piping:	n/a	V	Yes			\$
	Repair drain/waste/vent piping	n/a	✓	Yes			\$
	Repair water piping	n/a		Yes	V		\$ 300.00
	Repair/replace water heater	n/a		Yes	V	Gas line drip leg	\$ 100.00
	Other	n/a		Yes			\$

Other

n/a ☐ Yes ☐

Windows								
	Replace broken glass	n/a	V	Yes			\$	
	Repair or replace sash	n/a	V	Yes			\$	
Doors	Repair or replace doors	n/a		Yes	7		\$	800.00
						0.551		
Walls/Ceiling	Repair or repl. locks/latches	n/a	Ш	Yes	✓	Self Help	\$	240.00
viano, ocinii,	Repair or repl. @ defective	n/a		Yes	1		\$	300.00
Paint								
	Repair or repl. @ defective	n/a		Yes	√		\$	300.00
Fire Safety								
	Install smoke/CO alarm:bsmt.	n/a		Yes	✓	Self Help	\$	60.00
	Install smoke/CO alarm: 1st flr.	n/a		Yes	V	Self Help	\$	60.00
	Install smoke/CO alarm: 2nd flr.	n/a		Yes	V	Self Help	\$	60.00
Handrails	Repair/replace defective	n/a		Yes	7	Self Help	\$	250.00
Stairs	Tropali/Topiaco defectivo	TI/ CI		100	<u> </u>	Son Troip	Ψ	200.00
	Repair defective	n/a	V	Yes			\$	
Floors	Repair defective	n/a		Yes	7		\$	1,200.00
Other	<u></u>						· · ·	1,=0000
		n/a		Yes	√	Trim/millwork	\$	100.00
		n/a		Yes			\$	
		n/a		Yes			\$	
		n/a		Yes			\$	
						Interior: Estimated Cost:	\$	6,620.00
						Total Exterior and Interior Cost:*	\$	18,640.00
	*average contracted cost. Actual costs may vary. Self help will reduce the amount.							

Date: 9/1/2015 Inspected by: Mark Stack

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway.